ACS POST-DEPARTURE MODING CONFIGURATION

NOTE

For ISS assembly flight 2A, this procedure is to be performed by Ground only.

1. DISABLE LED MODE INDICATIONS AND VERIFY LED STATUS

NOTE

The functions in this section are to occur following the end of the orbiter Prox-Ops phase.

PCS MCS: ACS Moding

ACS Moding

'ACS Configuration'

sel LED Control SW Primary NCS - Command

cmd Inhibit Execute

√LED Control SW Primary NCS - Inh

√PMA2 LED State Primary NCS - Off

sel LED Control SW Secondary NCS - Command

cmd Inhibit Execute

√LED Control SW Secondary NCS - Inh

√PMA2 LED State Secondary NCS - Off

2. <u>DISABLE DEPARTURE RESPONSE</u>

'Departure'

PMA2 Departure Response SW Primary NCS - Command

cmd Inhibit Execute

√PMA2 Departure Response SW Primary NCS - Inh

sel PMA2 Departure Response SW Secondary NCS - Command

cmd Inhibit Execute

√PMA2 Departure Response SW Secondary NCS - Inh

√Departure Event Primary NCS - Blank

√Departure Event Secondary NCS - Blank